## Cyprus Thompson Creek

Post Office Box 62 Clayton, Idaho 83227 Telephone (208) 838-2200

July 12, 1988

JUL 19 1988

WATER PERMITS & COMPLIANCE BRANCH

EPA-REGION 10

Chief, Water Compliance Section EPA, Region 10, Mail Stop 513 1200 Sixth Avenue Seattle, Washington 98101

Re: Thompson Creek NPDES Discharge Monitoring Reports for June 1988 and Second Quarter Report - 1988

Dear Sir or Madam:

Enclosed are the discharge monitoring reports for June 1988, for discharge points 001 and 002 from the Thompson Creek Mine. Also enclosed are the second quarter results from the same sources.

If you have any questions, please contact us.

Sincerely,

Bert Doughty Supervisor

Environmental Affairs

year such


BD:bw

## ATTACHMENT A\*

## June 1988

## Turbidities on Thompson Creek

DATE	STATION	TURBIDITY (NTU)
6/16/88	TC-1	0.6
6/16/88	TC-2	0.5
6/16/88	TC-3	0.52
6/16/88	TC-4	0.55



WATER PERMITS & COMPLIANCE BRANCH EPA-REGION 10

<sup>\*</sup> When Buckskin isn't discharging